

## **PAINTMARKERS**




- Xylene-Free
- Permanent, durable, fast drying, lead-free paint
- Marking temperature range from -50°F to 150°F (-46°C to 66°C)



## PRIME-ACTION



- Industrial strength paint with rugged prime-action tip
- Fast-drying permanent paint
- Marks on all surfaces: Clean, dirty, oily



## **SOLID STICK**





- Fast-drying permanent marks

Marks THROUGH oil and water



**Plastic** 



